gearmo®

User Manual

10-Port USB 3.2 Gen 2 Hub w/ 6 Type-A Ports, 4 Type-C Ports, & ESD Protection   Model No.   GM-HU310CA

gearmo.com

Contents

Introduction

▶ Thank you for purchasing Gearmo's **Industrial 10-Port USB 3.2 Gen 2 Type-C Hub GM-HU310CA**! Please read the manual in detail first before you begin using this hub. The specifications are subject to change without notice.

System Requirements

▶ **Desktop** or **Notebook Computer** with an Available USB Type-A or USB Type-C Port
▶ **Windows 11** (32/64-bit), **Windows 10** (32/64-bit), **8** (32/64-bit), **7** (32/64-bit), **Vista** (32/64-bit), **XP** (32/64-bit)
▶ **Mac OS** Lowest or Latest Versions

Package Contents

▶ Industrial 10-Port USB 3.2 Gen Type-C & A Industrial Hub
▶ User Manual
▶ USB Type-C to Type-C Screw-Locking Cable
▶ DIN-Rail & Wall Mounting Kit
▶ 3-Pin Terminal Block
▶ Screw Package

Hub Layout

Downstream Port
6x USB Type-A

Upstream Port
USB Type-C
Screw-Lock

Downstream Port
4x USB Type-C
Screw-Lock

Terminal Block   **DC Power Jack**

Installation

1. Power
- The USB 3.2 Gen 2 Hub requires a **9-24V DC** external power source to work (not included).
- Power up the USB Hub through either the **DC Power Jack** or **3-Pin Terminal Block**.

2. 2-Pin Terminal Block
- Plug the included terminal block to the hub's terminal block connector.

3. Hardware
- Mount your hub on the **Wall, Surface or Din Rail**, if needed.

DIN Rail Mounting

▶ Use the included screws to install the DIN Rail Clip to the hub.

▶ Insert the top of the DIN Rail Clip onto the DIN Rail Track, then gently push the bottom of the hub to secure it to the DIN Rail Track.

Surface / Wall Mounting

▷ Use the included screws to mount the hub to the wall or smooth surface.

Specifications

- Supports all USB 1.1 to 3.2 compatible peripherals, max data transfer rate: 10Gbps
- 9-24V DC input
- LED indicate power on
- Support Systems Windows Vista/7/8/10/11/Mac OS
- Support USB 3.2 plug and play
- 15KV ESD surge protection
- Operating temperature 0-50° C